



Republika ng Pilipinas
Kagawaran ng Edukasyon
 Tangkapan ng Pangatawagang Kalihim

OUA MEMO 00-0221-0173
MEMORANDUM
 08 February 2021

100 22 173
 2021

For: **Regional Directors
 Schools Division Superintendents
 ESSD and SGOD Chiefs
 Regional and Division Engineers
 DepEd Project Engineers**

Subject: **REVISED REPAIR PARAMETERS FOR
 SCHOOL BUILDING REPAIR/REHABILITATION**

The impact of damages to the school facilities brought by the various calamities that hit different parts of the country has led the Education Facilities Division (EFD) to review the manner of repair works and its existing policies and guidelines for the repair/rehabilitation of School Buildings. As a result of damage assessments conducted, improvements on existing practices and policies must be implemented to ensure that repaired school buildings will have minimal damages during calamities.

Annex 1 – is the revised plans to be used for reference in the determination of repair works for various existing school building types.

Annex 2 – Updated template for the Program of Works following the revised plans in Annex 1

Annex 3 – Revised Repair Parameters Matrix
Annex 4 – Revised Damage Assessment Form


The above-stated documents shall guide the engineers/architects in the revision of the Program of Works for repair projects. The proposed repair improvements in the roofing include but are not limited to:

- Additional purlins at top and end of roofing;
- Use of J-bolts as fastener at top and end of roofing;
- Wider coverage of the ridge roll;
- Provision of angular bars at both sides of roofing; and
- Provision of aluminum foil insulation at roofing



Office of the Undersecretary for Administration (OUA)

Administrative Services, Information and Communications, Technology Services, and
 Procurement, Acquisition and Management Services (ADMMS), Division of Learning Support
 Services (DLSS), Regional Training Group (RTG), Central Office, Department of Education
 Department of Education - Central Office, Meriden Avenue, Pasig City
 1105 519 Mabini Bldg. Mobile: +639260320762, Tel: +632-85617213, Fax: 85617217
 Email: uas-admin@deped.gov.ph, Facebook/Twitter: @depedtas



Republic of the Philippines
CORRIERA ADMINISTRATIVE REGION
 Wangal, La Trinidad, Benguet

DEPED-CAR
 February 26, 2021

To: Schools Division Superintendent
 Division Engineers
 All Divisions

For information and strict compliance.
 Submission of Revised Repair POW-March 15, 2021.

[Signature]
ESTELA L. CARIÑO EdD, CESO III
 Regional Director


ESSD/EHMcbb



School buildings deemed to be demolished shall no longer be programmed for repair works.

The adoption of these documents shall be used in the implementation of BEFF-Repair 2021 and Quick Response Funds (QRF) 2021. Thus, the Damage Assessment Form (**Annex 4**) and the Revised Program of Works using the latest issued unit cost of construction materials must be prepared and submitted on a per school basis following the shortlisted schools identified by the respective Division Engineers for BEFF 2021 Repair/Rehabilitation.

The **deadline for the submission** shall be **on before February 18, 2021**. For any clarifications, please coordinate with the respective EFD Area Managers.

For compliance of all concerned.


ALAIN DEL B. PASCUA
Undersecretary



OUAD00-0221-0173
To authenticate this document
please scan the QR Code